

* If installing in very hot weather, increase these dimensions 1/8".

of-round.


requires hex crimping tool. Do Not crush cable out-ferrule with proper crimping tool. Hex connector connector on cable as far as it will go. Crimp built-in insulation (braid and foil, on foil shield cable) and push

STEP 3: Slide connector tip between braid and inner touch center conductor.

center conductor. Make sure no foil or braid can 1/4" of inner insulation being careful not to nick

STEP 2: Trim braid close to outer cover and remove cable. Fry braid back as far as outer cover will allow.



STEP 1: Strip outer cover back 1/2" from end of




INSTALLING FC-5910 CONNECTORS ON COAX CABLE

WAYS TO MOUNT COUPLER


UNDER EAVES



ON FLOOR



ON MAST



ON WALL

(continued other side)

Printed in U.S.A., 2451860 Rev. 3/97

other rights which vary from state to state.

This warranty gives you specific legal rights and you may also have apply to you.

Some states do not allow limitations on how long an implied warranty lasts, or the exclusion of incidental or consequential damages, so the above limitations or exclusions may not apply to you.

The foregoing shall be the sole and exclusive remedy of any person, whether in contract, tort or otherwise, and Winegard shall not be liable for incidental or consequential damage or commercial loss, or from any other loss or damage except as set forth above.

TO THE 90-DAY PERIOD OF THIS WARRANTY.

ALL OTHER WARRANTIES WHETHER EXPRESS, IMPLIED OR STATUTORY INCLUDING WARRANTIES OF FITNESS FOR A PARTICULAR PURPOSE AND MERCHANTABILITY ARE LIMITED BY ANY OTHER PERSON.

WINEGARD COMPANY WILL NOT ASSUME ANY LIABILITIES FOR ANY OTHER WARRANTIES, EXPRESS OR IMPLIED, MADE TO DEFECTIVE MATERIAL OR WORKMANSHIP.

equipment is properly delivered with all handling and freight charges prepaid to your Winegard dealer for return to our factory for repair or replacement. Winegard dealers will arrange for the replacement or repair and return to you without charge the product which failed due to defective material or workmanship.

The 90 Day Warranty is provided on the condition that the manufacturer has no control.

caused by wind, lightning, ice or other occurrences over which the have been subjected to misuse, improper installation, or to damage of the product. The warranty does not extend to products which does not cover any costs incurred in removal, shipping or reinstallation of the product at no charge to you. This warranty covers parts, but defective product at no charge to you. This warranty covers parts, but

Winegard Company (at its option) will either repair or replace the defective product at no charge to you. Telephone 800-286-8944. Burlington, IA 52601-2000. Please contact Winegard Company, 3000 Kirkwood Street, made, you present proof of purchase to an authorized Winegard dealer (if purchase. No warranty claim will be honored unless the time from date of defects in materials or workmanship within 90 (ninety) days from date of

CONSUMER 90 DAY WARRANTY

DESCRIPTION FOR SPLITTING A SINGLE COAX LINE FOR SECOND TV HOOK-UP

INSTRUCTIONS

STEP 1. Install FC-5910 connectors on coax cables per instructions on back of sheet.

STEP 2. Attach antenna downlead to jack marked "Antenna" and antenna cables to jacks marked "Set 1" and "Set 2".

STEP 3. Mount coupler with screws and bracket as shown.

Winegard Company
3000 Kirkwood St., Burlington, IA. 52601

Made in U.S.A.

Model CC-7870
(75 ohm)

67 CHANNEL 2-WAY ANTENNA TV SET COUPLER



INSTRUCTIONS

DESCRIPTION FOR COUPLING TWO ANTENNAS

The CC-7870 couples two 75 ohm leads from any two antennas to a 75 ohm downlead. Input and output are thru standard 75 ohm F-jacks. AC-DC passive input to Set 1 side. Three FC-5910 connectors provided. -3.5 insertion loss.

INSTRUCTIONS

STEP 1. Install FC-5910 connectors on coax cables per instructions on back of sheet.

STEP 2. Attach antenna downlead to jack marked "Antenna" and antenna cables to jacks marked "Set 1" and "Set 2". See illustration.

STEP 3. Mount coupler with screws and bracket as shown.

